

FLORIDA MASTER
SITE FILE

FDAHRM 802==

| | | |
|---|--|---------------|
| Site No. | <u>8Du 605</u> | <u>1009==</u> |
| Site Name | <u>223 W. Fifth Street</u> | <u>830==</u> |
| Other Name(s) for Site | _____ | <u>930==</u> |
| Other Nos. for Site | _____ | <u>906==</u> |
| NR Classification Category: | <u>building</u> | <u>916==</u> |
| County | <u>Duval</u> | <u>808==</u> |
| Instructions for locating site (or address) | <u>223 W. Fifth Street, Jacksonville, Florida</u> | |
| | | <u>813==</u> |
| Owner of Site: Name | <u>Jordan, Christie</u> | <u>902==</u> |
| Address | <u>1337 Rushing St., Jacksonville, Florida</u> | <u>903==</u> |
| Occupant, Tenant, or Manager: | | |
| Name | _____ | <u>904==</u> |
| Address | _____ | <u>905==</u> |
| Reporter (or local contact): | | |
| Name | <u>Bowman, Brian Grad. Ast.</u> | <u>816==</u> |
| Address | <u>802 N. Laura Street, Jacksonville, Florida</u> | <u>817==</u> |
| Recorder: | | |
| Name & Title | <u>Greer, Diane Historic Sites Specialist</u> | <u>818==</u> |
| Address | <u>FDAHRM, Tallahassee</u> | <u>819==</u> |
| Survey Date | <u>7406</u> <u>820==</u> Type Ownership <u>private</u> | <u>848==</u> |
| Inventory Status | _____ | <u>914==</u> |
| Previous Survey(s), Excavation(s) or Collection(s): | <i>(enter title of survey; date; whether federal, state, county or local; location of survey report(s); and material collected).</i> | |
| | | <u>839==</u> |
| | | <u>804==</u> |
| Recording Station | _____ | <u>870==</u> |
| Specimens (Inventory Numbers) | _____ | <u>880==</u> |
| Specimens (Present Repository of Materials) | _____ | <u>832==</u> |
| Date of Visit to Site | <u>7406</u> <u>828==</u> Recording Date <u>7406</u> | <u>832==</u> |
| Photographic Record Numbers | <u>74-N-09-11</u> | <u>860==</u> |

**SEE SITE FILE STAFF FOR
ORIGINAL PHOTO(S) OR MAP(S)**

DU605

Location of Site (Specific):

Map Reference (incl. scale & date) USGS Jacksonville Quad. 7.5min. 1964 809==

| Township | Range | Section | ¼ Sec. | ¼ ¼ Sec. | ¼ ¼ ¼ Sec. |
|----------|-------|---------|-----------------|----------|------------|
| T02S | R26E | S37 | ()irregular() | | |

812==

LATITUDE AND LONGITUDE COORDINATES DEFINING A POLYGON LOCATING THE PROPERTY

| Point | LATITUDE | | | LONGITUDE | | |
|-------|--------------|--------------|--------------|--------------|--------------|--------------|
| | Degrees ° | Minutes ' | Seconds " | Degrees ° | Minutes ' | Seconds " |
| | ° | ' | " | ° | ' | " |
| | ° | ' | " | ° | ' | " |
| | ° | ' | " | ° | ' | " |
| | ° | ' | " | ° | ' | " |
| | ° | ' | " | ° | ' | " |

OR

LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES

| | | | | | |
|---|---|---|---|---|---|
| ° | ' | " | ° | ' | " |
|---|---|---|---|---|---|

800==

UTM Coordinates: 17 436710 3356700 890==
Zone Easting Northing

Description of Site:

Original Use(s) of Site private residence 838==

Site Size (approx. acreage of property) LT 1 833==

| | |
|--|--|
| <p>Condition of Site:</p> <p>Check one</p> <p><input type="checkbox"/> Excellent 863== <input type="checkbox"/> Deteriorated 863==</p> <p><input checked="" type="checkbox"/> Good 863== <input type="checkbox"/> Ruins 863==</p> <p><input type="checkbox"/> Fair 863== <input type="checkbox"/> Unexposed 863==</p> | <p>Integrity of Site:</p> <p>Check one or more</p> <p><input type="checkbox"/> Restored () Date: () 858==</p> <p><input checked="" type="checkbox"/> Altered 858== <input type="checkbox"/> Moved () Date: () 858==</p> <p><input type="checkbox"/> Unaltered 858== <input checked="" type="checkbox"/> Original Site 858==</p> <p><input type="checkbox"/> Destroyed 858==</p> |
|--|--|

Condition of Site (Remarks): _____

863==

Threats to Site: _____

878==

ARCHITECTURAL SITE DATA SUPPLEMENT

ARCHITECT unknown' 872==

BUILDER unknown 874==

STYLE AND/OR MODE late Victorian 964==

PLAN TYPE central hall 966==

EXTERIOR FABRIC(S) horizontal wood siding 854==

STRUCTURAL SYSTEM(S) wood frame 856==

FEATURE OF STRUCTURE (942):

FOUNDATION: concrete block 942==

ROOF TYPE: hip 942==

SECONDARY ROOF STRUCTURE(S): dormer centrally located on south facade

942==

WINDOW TYPE: double-hung sash 942==

MATERIALS (882):

CHIMNEY: none 882==

ROOF SURFACING: asphalt shingle 882==

INTERIOR WALLS: plaster 882==

ORNAMENT INTERIOR: not accessible 882==

ORNAMENT EXTERIOR: wood cornice, painted trim 882==

QUANTITATIVE DATA (950-960):

NO. OF STOREYS 2½ 950==

NO. OF CHIMNEYS none 952==

OTHER (SPECIFY) 954==

956==

OTHER NOTABLE FEATURES OF BUILDING (FREE TEXT) (865):

ROOF STRUCTURAL SYSTEM:

865==

MAIN ENTRANCE: single door with light in upper and side light and transom to left of enter in front

865==

WINDOW PLACEMENT: regular

865==

WINDOW SURROUNDS AND DECORATION: surrounds

865==

PORCHES, VERANDAS, GALLERIES AND BALCONIES: One story porch on south facade and around south east/west corners of building with railings ; pedestals of cast concrete block as ashlar; support columns hold roof of porch having a cornice with modillions

EXTERIOR ORNAMENT AND COLOR:

building is white with plain roof cornice

865==

INTERIOR COMMENTS: not accessible

865==

OTHER (SPECIFY): structure is in good condition

865==

MAJOR ALTERATIONS (FREE TEXT) awning covering porch entrance added

857==

OUTBUILDINGS (FEATURES OF SITE) none

876==

SURROUNDINGS (CLASSIFICATION) residential

864==*

RELATIONSHIP TO SURROUNDINGS (FREE TEXT) structure is located mid-block on north side of W, 5th St. surrounded by buildings of comparable scale

859==

HISTORIC SITE DATA SUPPLEMENT

Site Name 223 W. Fifth St.

Present Use (check one or more as appropriate)

| | | | |
|--|---|---|---|
| <input type="checkbox"/> Agricultural 850== | <input type="checkbox"/> Government 850== | <input type="checkbox"/> Park 850== | <input type="checkbox"/> Transportation 850== |
| <input type="checkbox"/> Commercial 850== | <input type="checkbox"/> Industrial 850== | <input checked="" type="checkbox"/> Private Residence 850== | Other (Specify): |
| <input type="checkbox"/> Educational 850== | <input type="checkbox"/> Military 850== | <input type="checkbox"/> Religious 850== | <input type="checkbox"/> _____ 850== |
| <input type="checkbox"/> Entertainment 850== | <input type="checkbox"/> Museum 850== | <input type="checkbox"/> Scientific 850== | <input type="checkbox"/> _____ 850== |

Period (check one or more as appropriate)

| | | | |
|--|---|---|--|
| <input type="checkbox"/> Pre-Columbian 845== | <input type="checkbox"/> 16th Century 845== | <input type="checkbox"/> 18th Century 845== | <input checked="" type="checkbox"/> 20th Century 845== |
| <input type="checkbox"/> 15th Century 845== | <input type="checkbox"/> 17th Century 845== | <input type="checkbox"/> 19th Century 845== | |

Specific Dates: Beginning _____ **844==** **Ending** _____ **846==**

Areas of Significance (check one or more as appropriate)

| | | | |
|---|--|---|---|
| <input type="checkbox"/> Archaeology Prehistoric 910== | <input type="checkbox"/> Conservation 910== | <input type="checkbox"/> Literature 910== | <input type="checkbox"/> Social/Human- itarian 910== |
| <input type="checkbox"/> Archaeology Historic 910== | <input type="checkbox"/> Economics 910== | <input type="checkbox"/> Military 910== | <input type="checkbox"/> Theater 910== |
| <input type="checkbox"/> Agriculture 910== | <input type="checkbox"/> Education 910== | <input type="checkbox"/> Music 910== | <input type="checkbox"/> Transportation 910== |
| <input checked="" type="checkbox"/> Architecture 910== | <input type="checkbox"/> Engineering 910== | <input type="checkbox"/> Philosophy 910== | Other (Specify): |
| <input type="checkbox"/> Art 910== | <input type="checkbox"/> Industry 910== | <input type="checkbox"/> Politics/Govt. 910== | <input type="checkbox"/> _____ 910== |
| <input type="checkbox"/> Commerce 910== | <input type="checkbox"/> Invention 910== | <input type="checkbox"/> Religion 910== | <input type="checkbox"/> _____ 910== |
| <input type="checkbox"/> Communications 910== | <input type="checkbox"/> Landscape Architecture 910== | <input type="checkbox"/> Science 910== | <input type="checkbox"/> _____ 910== |
| <input type="checkbox"/> Community Planning 910== | <input type="checkbox"/> Law 910== | <input type="checkbox"/> Sculpture 910== | <input type="checkbox"/> _____ 910== |

Thematic Classification:

| | | |
|---|---|--------------------------------------|
| <input type="checkbox"/> Aboriginal 912== | <input type="checkbox"/> Military 912== | Other (Specify): |
| <input checked="" type="checkbox"/> Architectural 912== | <input type="checkbox"/> Political 912== | <input type="checkbox"/> _____ 912== |
| <input type="checkbox"/> The Arts 912== | <input type="checkbox"/> Society 912== | <input type="checkbox"/> _____ 912== |
| <input type="checkbox"/> Exploration & Settlement 912== | <input type="checkbox"/> Science & Technology 912== | <input type="checkbox"/> _____ 912== |

Statement of Significance (use continuation sheet if necessary)

The structure located at 223 W.5th St. in Springfield is believed to have been constructed in the first years of the twentieth century and remains in good condition today. The outstanding characteristic of the building is the porch that spans the entire south facade and dominates the front appearance. The structure is still used today for residential living and was chosen for this inventory because of its architectural significance in the surrounding area.

911==

Remarks & Recommendations:

835==

Major Bibliographic References:

on site inspection

920==

Description (Evidence):

862==

Present & Original Physical Appearance (use continuation sheet if necessary)

SEE ATTACHED ARCHITECTURAL SITE DATA SUPPLEMENT

935==



00665

Brentwood

JACKSONVILLE

Brookline

San Marco

South Jacksonville

RIVER

INTERCHANGE 3

INTERCHANGE A

INTERCHANGE 2

INTERCHANGE 10

INTERCHANGE 9

SEABOARD

AIR LINE

SEABOARD COAST LINE

HUGANSON

JOHNS

ST. JOHN'S



8 Du 605

Site Name 223 West 5th Street

830

Other Name(s) for Site _____
_____ 930

Other Nos. for Site _____ 906

Type of Site Building _____ 832

Location of Site:
County Duval _____ 808

Instructions for locating site (or address) 223 W. 5th Street
Jacksonville, Florida
_____ 813

Ownership:
Owner of Site: Name Christie Jordan _____ 902

Address 1337 Rushing Street _____ 903
Jacksonville, Florida

Occupant, Tenant or Manager:
Name _____ 904

Address _____ 905

Form Prepared By:
Reporter (or local contact):
Name Bowman, Brian, Graduate Asst. _____ 816

Address 802 Laura Street _____ 817
Jacksonville, Florida

Recorder:
Name & Title Greer, Diane D., HSS _____ 818

Address FDAHRM, Tallahassee, Florida _____ 819

Date of Site Survey 6-74 _____ 820

Previous Survey(s), Excavation(s) or Collection(s): *(enter title of survey, date, whether federal, state, county or local, location of survey report(s) and material collected).*

N/A

839

Photographic Record Numbers _____
_____ 860

| | | | | | |
|----------|-------|---------|----------|--------------|------------------|
| TOWNSHIP | Range | Section | 1/4 Sec. | 1/4 1/4 Sec. | 1/4 1/4 1/4 Sec. |
| 2S | 26E | 37 | | | |
| | | | | | 812== |

| | | | | | | |
|--|-------------------------|-------------------------|-------------------------|---|-------------|--|
| LATITUDE AND LONGITUDE COORDINATES DEFINING A POLYGON LOCATING THE PROPERTY | | | O R | LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES | | |
| CORNER | LATITUDE | LONGITUDE | | LATITUDE | LONGITUDE | |
| | Degrees Minutes Seconds | Degrees Minutes Seconds | Degrees Minutes Seconds | Degrees Minutes Seconds | | |
| | ° ' " | ° ' " | ° ' " | ° ' " | | |
| | ° ' " | ° ' " | ° ' " | 30° 20' 31" | 81° 39' 25" | |
| | ° ' " | ° ' " | ° ' " | | | |
| | ° ' " | ° ' " | ° ' " | | | |
| | ° ' " | ° ' " | ° ' " | | | |
| | ° ' " | ° ' " | ° ' " | | | |
| | | | | | 812== | |

Global Reference Code _____ 884==

Description of Site:
 Site Size (approx. acreage of property) less than one 833==

Present Condition of Site

| | | | | | |
|------------------------------------|-------|---------------------------------------|-------|--|-------|
| Check one | | Check one | | Check one if appropriate | |
| <input type="checkbox"/> Excellent | 863== | <input type="checkbox"/> Deteriorated | 863== | <input type="checkbox"/> Moved | 863== |
| <input type="checkbox"/> Good | 863== | <input type="checkbox"/> Ruins | 863== | <input type="checkbox"/> Original Site | 863== |
| <input type="checkbox"/> Fair | 863== | <input type="checkbox"/> Unexposed | 863== | | |
| | | <input type="checkbox"/> Altered | 863== | | |
| | | <input type="checkbox"/> Unaltered | 863== | | |

Present & Original Physical Appearance (use continuation sheet if necessary)

See attached sheet for complete architectural description.

875==

RELATION OF STRUCTURE TO SITE AND SURROUNDINGS single lot on north side of West 5th Street closely flanked by other dwellings


FOUNDATION (TYPE AND MATERIALS) concrete block

STRUCTURAL SYSTEM wood frame

EXTERIOR FABRIC (BOND TYPE, IF BRICK) horizontal wood siding

NUMBER OF STORIES 2½

PLAN (DRAW) _____



ROOF TYPE AND COVERING MATERIAL hip with asphalt shingles

DORMERS AND SECONDARY ROOF STRUCTURES dormer centrally located on front

CHIMNEYS (NUMBER, LOCATION, MATERIALS) _____

MAIN ENTRANCE (LOCATION, DESIGN) single door with light in upper half and side light and transom to left of center of front

SUBSIDIARY ENTRANCES single door in rear

FENESTRATION (TYPE) sash

WINDOW SURROUNDS, LINTELS, SHUTTERS surrounds

PORCH (HEIGHT, WIDTH, ROOF, SUPPORTS, ENCLOSURES, TYPE, MATERIALS) 1 story runs across front (south) and around southeast and southwest corners - railings - pedestals of concrete block cast as ashlar support columns holding porch roof having a cornice with modillions

EXTERIOR ORNAMENT AND COLOR building white; plain roof cornice

INTERIOR COMMENTS _____

CONDITION good

ALTERATIONS _____

OUTBUILDINGS none

STYLE AND/OR PERIOD _____

ARCHITECTURAL SIGNIFICANCE AND IMPRESSIONS _____